



JON M. HUNTSMAN, JR.
Governor
GARY R. HERBERT
Lieutenant Governor

State of Utah

DEPARTMENT OF NATURAL RESOURCES

Division of Oil, Gas & Mining

MICHAEL R. STYLER
Executive Director

MARY ANN WRIGHT
Acting Division Director

Supervisor DR7

Inspection Report

Minerals Regulatory Program

Report Date: February 14, 2005

Mine Name: Rhyolite #1

Operator or Permittee Name:

Color Country Rock

Permittee Mailing Address:

115 South Main

Veyo, Utah 84782

Inspector(s): Doug Jensen

Other Participants: None

Permit Status: Inactive

Current Acreages:

Total Permitted (Bonded): <5 Acres

Total Disturbed: <5 Acres

Permit number: S/021/032

Inspection Date: February 1, 2005

Weather: Cool, windy, cloudy

Inspection Start Time: 10:00 AM

Inspection End Time: 10:15 AM

Site location/Area Inspected (i.e. Pit #):
Site

Surface Ownership: BLM

Mineral Ownership: BLM

Mineral Mined: Rhyolite

Type of Mine: Open Pit

Elements of Inspection	Evaluated	N/A	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (open shafts, adits, trash, signs, highwalls)	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Explosives, magazines	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Deleterious Material	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Roads (maintenance, surfacing, dust control, safety)	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Concurrent Reclamation	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Erosion Control	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Demolition	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Backfilling and Grading (trenches, pits, roads, highwalls, shafts, drill holes)	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
11. Water Impoundments	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12. Soils	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
13. Revegetation	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
14. Air Quality	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
15. Facilities	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
16. Other	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Inspection Date: February 1, 2005; Report Date: February 14, 2005

Page 2 of 2

S/021/032

Purpose of Inspection:

While in the area, I stopped to check the site.

Inspection Summary:

Check the stability of the site.


Directions to the site:

The site is located ~4 miles east of Highway 56, 1 mile north of the highway.

GPS data:

None gathered

Inspector's Signature



Date: February 14, 2005

DJ:jb

Enclosures:

cc: Preston Hafen, Color Country Rock
Ed Ginouves, BLM, Cedar City FO

O:\M021-Iron\S0210032-RhyoliteQuarry\inspections\02012005ins.doc